sunnova



Submission

System ID: *DF001054878*

Carlos Mauras Diaz H9 BO BAJOS CARR 3 KM 119 PATILLAS, PR 00723 **APPROVED**

08/03/2016 2:34 PM Roof Micro Maximo Solar

Edwin Vargas evargas@maximosolar.com (787) 891-8080

1. Roof Array(s)



IMG-20160726-WA0012.jpg



IMG-20160726-WA0009.jpg

2. Module Attachments



IMG-20160726-WA0028.jpg



IMG-20160726-WA0026.jpg

3. Array Tilt

APPROVE



IMG-20160726-WA0007.jpg

4. Roof Underneath Array (Micro)

APPROVE



IMG-20160726-WA0014.jpg

5. Roof Flashing

APPROVE



IMG-20160726-WA0020.jpg

6. Roof Structural



IMG-20160726-WA0015.jpg



IMG-20160726-WA0023.jpg

8. Roof Conduit Run

APPROVE



IMG-20160726-WA0019.jpg

9. Roof Conduit Penetration

APPROVE



IMG-20160726-WA0034.jpg



10. Home Run Conduit

Case 3:18-cv-01068-ADC Document 20-2 Filed 04/13/18 Page 4 of 5



IMG-20160726-WA0011.jpg

11. AC Combiner Panel

APPROVE



IMG-20160726-WA0044.jpg

12. Microinverters

APPROVE



IMG-20160726-WA0016.jpg

13. Microinverter Serial Numbers



IMG-20160726-WA0017.jpg

Case 3:18-cv-01068-ADC Document 20-2 Filed 04/13/18 Page 5 of 5

14. AC Disconnect



IMG-20160726-WA0046.jpg

15. Sunnova Monitor

APPROVE



IMG-20160726-WA0010.jpg

16. Interconnection (tap or backfeed)



IMG-20160726-WA0004.jpg